


7 Replacement Tips



Note)
 Since the heater is integrated in the tip, replacement of only the heater or the tip is not possible.

The RX-80HRT-2CD and RX-80HRT-3CD cannot be sold or used in the U.S. Therefore, please do not take them to or use them in the U.S.

8 Replacement Parts

For replacement parts, contact a *goot* distributor.

NO.	Item	Parts No.	Note
1	RX-802AS Soldering unit	RX-80GAS	(Tip is not included)
2	Soldering Iron Stand Sponge	ST-53SP	Replacement sponge for ST-20