



IXYS Corporation USA

May 22, 2013

## **Certificate of Compliance RoHS**

Herewith we confirm that all

IXYS Devices and Chip Products

do not contain any detectable amount of the substances

Pb, Cd, Hg, CR6+, HBCDD, DEHP, DBP and BBP

and do comply with the requirements detailed in the

**DIRECTIVE 2011/65/EU of the EUROPEAN PARLIAMENT and of the COUNCIL**

A handwritten signature in black ink that reads "Gordon Rosete".

Gordon Rosete  
IXYS Corporation  
Head of Quality Dept.  
1590 Buckeye Drive  
Milpitas, CA USA 95035